

CONVERSION FACTORS FOR WEAPONS GRADE PLUTONIUMTable 2. Approximate Factors for Converting Alpha Readings for Various Surface Types

Type of Surface	Correction Factor
Soil	.006
Concrete	.005
Plywood	.004
Stainless Steel	.0025