

CONTAMINATION CONTROLTable 1. CCS Materials List

Equipment	Quantity
Alpha particle monitoring equipment	4
Lighting for night operations	as needed
Low-level beta and/or gamma monitoring instrument	4
Dosimeters	as needed
2-inch or wider masking tape	3 rolls
NBC marking kit or substitute	1
Stools or chairs	4
55-gallon drums or equivalent for storing contaminated items	4
Plastic bags; sized to fit the barrels and/or drums used	20
Brushes	4
Whisk brooms	4
Shovels	4
Traffic cones, ropes, and stakes	as needed
Protective masks (SCBA, if available)	as needed
Personal Protective suits	as needed
Cotton gloves	as needed
Booties or foot covers	as needed
Water container; 5 gallons or larger	1
Paper towels or substitute	as required
Liquid soap; 1 gallon or more	1
Tables	5
Craft paper, butcher paper, or substitute	1 roll
Rain suits, ponchos, or substitute	as needed
Surgical masks	1 box
Organic solvents; 1 gallon or more	1
Large tent (20 or 40 men) or trailer with popup sun covers	as needed
Portable generator (as needed)	1
Portable heaters, air-conditioners, fans	as needed
Blankets	as needed
Litters	4
Non-slip plastic sheeting	1 roll
Bar Soap (Dozen) and/or Shampoo	as needed
Towels	as needed
Cotton Swabs	as needed
Bioassay Containers	as needed
Hair Brushes	as needed